	4	Appro	ved For Relea	ase 2002/06/18 : CIA	RDP74B00447R0	<u>0</u> 0100010033-	5		
	1000 164 1	5% 1 5 Ma	IR 66	SECRE	T	I DET	1 CC 1 RS		
25X1A		IRECTOR	yag) i membatan ayasaliyas arasa	34 ²	7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	DOS H	Z is ''.') 4 is in the second		
25X1A	tgo į	OR: 1736	SZ 15 MAF	R 66	70 	140	IN 9362.4 25X1A		
25X1A 25X1A 25X1A	i we	ALIST	25	₩		ote] 25X1A		
25X1A 25X1A			REPOI	RT AND PIECES OF A					
	THOSE PIECES AT ARE FOR PURPOSES OF 25X1A ANALYSIS. MAJOR SECTIONS NOT FOUND CONSIST OF THE LEFT HORIZONTAL STABILIZER, SUMP TANK, COCKPIT CANOPY AND THE PILOTS								
	STA SEA	Т.		K, COCKPIT CAN	:		1.EFT		

VING FROM ABOUT 100 FEET ABOVE GROUND DURING FIRST RECOVERY ATTEMPT.

THE SITE OF RECOVERY WAS ON THE LEE SIDE OF A RIDGE AND A DOWN
SLOPE WIND CONDITION EXISTED. THIS WHEN AGGRIVATED BY THE AIR

TURBULANCE CAUSED BY THE CHOPPER WHILE IN HOVER APPARENTLY CAUSED

THE WING TO BEHAVE IN AN UNSTABLE MANNER AT TIME OF PICK UP. THUS,

THE PILOT ELECTED TO DROP THE WING. IN MY OPINION, THE CHOPPER

PILOT MADE THE RIGHT DECISION. AS A RESULT, THE WING BROKE AT

A POSITION ROUGHLY SIX FEET FROM THE WING TIP. A NEW SLING

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010033-5

25X1A	S Sunt		<	FCR	FI	TH 93624	
-	ARRANGEMENT	WAS HISED	ON THE	SECOND	RECOVERY	WITH SUCCESS.	

25X1A

- 3. HELICOPTER SEARCH FOR THE STILL MISSING SECTIONS HAVE
 BEEN DISCONTINUED ON THE PASIS OF NOT PEING PROFITABLE. GROUND
 SEARCH BY TWO PEOPLE ON HORSEBACK CONTINUES. EXPECT TO DISCONTINUE
 THIS TYPE SEARCH LATER THIS WEEK. EXACT DATE DEPENDS ON HOW LONG
 IT TAKES THIS PARTY TO ACCOMPLISH ASSIGNED TASKS.
- 4. PLANNED DATE FOR DISTRIBUTION OF THE INVESTIGATING OFFICERS REPORT IS 18 MARCH 1966.
- 5. LATER THIS MONTH WE PLAN TO FORWARD A RESUME OF LESSONS LEARNED.

END OF MESSAGE

SECRET